

SYMBOL / ZEBRA LS2208 Barcode scanner

The programming manual can be downloaded from

https://www.zebra.com/content/dam/zebra_new_ia/en-us/manuals/barcode-scanners/ls2208-prg-en.pdf

You will need to download one of the CDC drivers from:

<https://www.zebra.com/us/en/support-downloads/software/drivers/usb-cdc-driver.html>

To enable the POS device manager to use USB-serial port, scan the following.



USB CDC Host

The scanner should reboot, and then create a virtual serial port in the Windows Device manager.

Select that serial port in the Windward Remote POS device manager.

To revert to USB-Keyboard/HID mode scan



***USB HID Keyboard**